



Attorney Docket No. 1293.1879
cfc

IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent Application of:

In-sik SEO

Application No.: 10/647,136

ATTENTION

Confirmation No.: 1050

CERTIFICATE OF CORRECTION

Filed: August 25, 2003

BRANCH

U.S. Patent No.: 6,885,835

Issued: April 26, 2005

For: DEVICE FOR CUTTING OFF POWER SUPPLY OF PRINTER

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents
PO Box 1450
Alexandria, VA 22313-1450

Sir:

Patentee respectfully requests that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: NOV. 15, 2005

By: 
Gene M. Garner, II
Registration No. 34,172

1201 New York Ave, N.W., Suite 700
Washington, D.C. 20005
Telephone: (202) 434-1500
Facsimile: (202) 434-1501

NOV 21 2005

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE
CERTIFICATE OF CORRECTION

PATENT NO : 6,885,835

DATED : April 26, 2005

INVENTOR : In-sik SEO

Column 10, line 23, after "unit" change ":" to --,--.

MAILING ADDRESS OF SENDER:
STAAS & HALSEY LLP
1201 New York Ave., N.W.
Suite 700
Washington, DC 20005

PATENT NO. 6,885,835

No. of add'l copies
@ 50¢ per page

⇒

NOV 21 2005